

# **interface**

**ADVANCED FORCE MEASUREMENT**

## **4 channel measuring amplifier BSC4D**

**USB Version  
Operating Instructions  
15-183 Revision A**

## mV/V measuring amplifier BSC4-USB



BSC4D-Cxx (M12)  
Front view sensor connection



BSC4D-Dxx (SUB-D37)  
Front view sensor connection

- 4-channels
- Power supply via USB port
- Inputs for mV/V / 0–5 V
- Measurement ranges 2 mV/V / 10 mV/V
- DMS quarter / half / full bridges
- 8 digital inputs / outputs
- Data rate 0 Hz–125 Hz

### Description

This 4-channel measuring amplifier for sensors with strain gauges is equipped with a USB interface. The DC supply voltage for the unit is provided via the USB port at the back of the measuring amplifier. The measuring amplifier can be delivered with an SUB-D37 connection or with 4x M12 ports. The unit also has eight digital inputs and outputs.

## Dimensions

(See page 32 for mounting instructions)

Figure 1: Dimensions BSC4D-Dxx (SUB-D37)





Figure 2: Dimensions BSC4D-Cxx (M12)




## Technical data

1.Accuracy class	<b>0.05</b>	%
<b>Inputs</b>		
Resolution	16	Bit
DMS inputs		
Full bridge	350-5000	Ohm
Half bridge	350-5000	Ohm
Quarter bridge	120 / 350 / 1000	Ohm
Common mode rejection at 60 Hz common-mode signal	95–110	dB
<b>Measurement frequencies</b>		
Data frequency	0–125	Hz
Sampling frequency	1.92	MHz
Cut-off frequency		
analog	1000	Hz
digital	Notch filter	Hz
<b>Outputs</b>		
Bridge supply voltage	2.5	Volt
Current load capacity	10	mA
Fixed voltage output	5	V
Current load capacity	20	mA
Switching outputs/inputs	TTL level	
I/O 1-8	5 (active High)	V
Current load capacity:	5	mA
Interface	USB 1.1, USB 2.0 compatible	
Supply voltage		
Nominal range	4.5...5.5 via USB port	V DC
Isolation voltage	1000	Vrms
Current consumption	< 200	mA
<b>Temperature range</b>		
Nominal temperature range	-10...+65	°C
Storage temperature range	-40...+85	°C
Zero point drift	< 0.05	%/10°C
Sensitivity drift	< 0.01	%/10°C
<b>Dimensions</b>		
L x W x H	106 x 119 (132) x 32	mm
<b>Protection type / Weight</b>		
Protection type	IP40	
Weight BSC4-USB SUB-D37	239	g

Table 1: Technical data BSC4D

**Connection plan for 37-pin D-sub port**



	BSC4D-Dxx assignment	37-pin D-sub port (PIN No.)			
		Channel 1	Channel 2	Channel 3	Channel 4
+US	positive sensor supply	20	2	11	29
+UD	positive differential input	22	4	13	31
QB1000	quarter bridge extension 1kOhm	23	5	14	32
HB	half bridge extension	24	6	15	33
-UD	negative differential input	25	7	16	34
-US	negative sensor supply	27	9	18	36
UE	analog input	28	10	19	37
	screen	1	1	1	1

Table 2: Analog inputs

**Connection assignment for BSC4D-Cxx (M12)**

**5-pin port M12x1, type 763**


Top view:



5-pin	Description	Color code for cables
2	-US negative bridge supply	white
1	+US positive bridge supply	brown
3	+UD positive differential input	blue
4	-UD negative differential input	black
5	AUXin input without cable	grey

### Connection of full bridge with SUB-D37 version


The following graphics show the connection of a full bridge to channel 1 through to channel 4.



### Connection of half bridge with SUB-D37 version

The following graphics show the connection of a half bridge to channel 1 through to channel 4.


The bridge extension should be adapted depending on the application.



### Connection of quarter bridge with SUB-D37 version

The following graphics show the connection of a quarter bridge to channel 1 through to channel 4.

The bridge extension should be adapted depending on the application.






### Connection of full bridge with M12 version

The following graphic shows the connection of a full bridge for the M12 version.

Full Bridge - M12



### Connection of half bridge with M12 version


The following graphic shows the connection of a half bridge for the M12 version.

The bridge extension should be adapted depending on the application.

<p>Half Bridge - M12</p> <p>■ HB1 Close the jumper on the PCB</p>	<p><b>Please set the solder bridges:</b></p> <ul style="list-style-type: none"> <li>●HB1 when using channel 1 with a half bridge.</li> <li>●HB2 when using channel 2 with a half bridge.</li> <li>●HB3 when using channel 3 with a half bridge.</li> <li>●HB4 when using channel 4 with a half bridge.</li> </ul> <p>Solder bridges: Figure 3: Solder bridges for configuring bridge extensions see page 11</p>
---	---

## Connection of quarter bridge with M12 version

The following graphic shows the connection of a quarter bridge for the M12 version. The bridge extension should be adapted depending on the application.



## Configuring the channel sensor impedance

The bridge sensor impedance can be configured individually for each channel; open the device and configure the desired solder bridge according to the following figure.





Figure 4: Solder bridges for configuring bridge impedance

## Altering from mV/V input to a voltage input



**Input conversion**  
From: mV/V  
To: 0-10 V

**Step 1**  
Remove the solder jumper(s) as shown in blue.

(the example shows 350 ohm bridge selections)

**Step 2**  
Add the voltage input solder jumper shown in red.

**Description**  
K1 for Channel 1  
K2 for Channel 2  
K3 for Channel 3  
K4 for Channel 4


## Opening the device

1. Remove both screw covers from the input side and remove the fastening screws from the front cover.
2. The two hexagonal bolts on the 37-pin D-Sub port must be loosened using a socket spanner (5 mm).
3. The printed circuit board is pulled out on the side of the 25-pin D-Sub port.

## Wiring diagram for position sensors

The measuring amplifier BSC4D must be configured by the manufacturer separately when using it with potentiometric position sensors (linear potentiometers or draw wire displacement sensors) for the M12 version.

The position sensor's wiper is connected to the measuring amplifier's "Aux" input (M12) or "U" (SubD37). The position sensor supplies via the sensor supply +Us and -Us.



The potentiometric position sensor is supplied with 2.5 V.  
The "Aux" input or U<sub>E</sub> records voltages of 0...5 V.

E

## Connection assignment

Label	5-pin port	37-pin D-SUB port				
		CH 1	CH 2	CH 3	CH 4	
positive supply +Us	1	positive supply +Us	20	2	11	29
negative supply -Us	2	negative supply -Us	27	9	18	36
"Aux" input	5	U <sub>E</sub> input	28	10	19	37

**Connection of the Way Con – draw wire sensor SX**


<b>4-pin port Waycon draw wire sensor SX</b>	<b>5-pin port</b>	<b>Label</b>	<b>Color code M12 sensor- actuator cable</b>		
1 (+supply)	1	positive supply +Us	brown		
3 (GND)	2	negative supply -Us	blue		
2 (wiper)	5	“Aux” input	white		
<b>4-pin port Waycon draw wire sensor SX</b>	<b>37-pin D-SUB port</b>				
	<b>CH 1</b>	<b>CH 2</b>	<b>CH 3</b>	<b>CH 4</b>	
1 (+supply)	20	2	11	29	pos. supply +Us
3 (GND)	27	9	18	36	neg. supply -Us
2 (wiper)	28	10	19	37	U input E

### Connection assignment SUB-D25 port


BSC4D assignment	25-pin D-sub port (PIN-No.)			
IO 5 V fixed voltage output	1			
IO GND	2			
IO 1	3			
IO 2	4			
IO 3	5			
IO 4	6			
IO 5	7			
IO 6	8			
IO 7	9			
IO 8	10			
TX	11			
RX	12			
GND	13			
	Channel 1	Channel 2	Channel 3	Channel 4
Channel GND	14	17	20	23
	15	18	21	24
Channel AUX	16	19	22	25

## Wiring diagram

### mV/V full bridge




### mV/V half bridge





## mV/V quarter bridge




	ch 1	ch 2	ch 3	ch 4
+Ud	3	14	25	36
-Us	5	16	27	38
HBx	8	19	30	41
AUX	6	17	28	39
QB 120	11	22	33	44
QB 350	10	21	32	43
QB 1000	9	20	31	42
Sw.	1	12	23	34

The active strain gage R4 is connected to the terminals +Ud, AUX and -Us in 3-wire technology.


HBx: The solder bridges “8”, “19”, “30” or “41” must be closed so that the internal bridge completion resistors R1 and R2 are activated.

A solder bridge should be set depending on the DMS resistance (120/350/1000 Ohm), e.g. 120 Ohm at channel 1: Solder bridge 11 (vertical); 350 Ohm at channel 2: Solder bridge 21 (horizontal).

### Voltage input 0-5 V

		<b>ch 1</b>	<b>ch 2</b>	<b>ch 3</b>	<b>ch 4</b>
		7	18	29	40
	-Us	5	16	27	38
	Sw.	1	12	23	34

### Voltage input 0-10 V

		<b>ch 1</b>	<b>ch 2</b>	<b>ch 3</b>	<b>ch 4</b>
		7	18	29	40
	-Us	5	16	27	38
	Sw.	1	12	23	34

## Programming / configuration

### Scaling of measured values

Each channel can be configured individually for a defined measuring range, e.g.

For measuring

- with wire strain gauges 2 mV/V,
- with wire strain gauges 10 mV/V,
- with active sensors 0-5 V,
- with temperature sensors PT1000,
- with type K thermocouples,
- with active sensors 0–10 V,

The measuring range is set using the command “set\_gain”.

105% of the input signal matches a value range of 0x0000 to 0xFFFF.

### Measuring range 2.0 mV/V

**Measuring range ±2 mV/V (set\_gain 0xB2 <p1> <p2>) with p1=ch, p2=0x01**

<i>Input signal in mV/V</i>	<i>Measuring range in %</i>	<i>16 Bit output value (hexadecimal)</i>
2.1	105.00%	FFFFh
2.0	100.00%	F9E7h
0.0	0.00%	8000h
-2.0	-100.00%	0618h
-2.1	-105.00%	0000h

Conversion of digital output value to analogue input signal:

Output value = Highbyte \* 256 + Lowbyte;

Input signal  $U_d = (\text{output value} - 32768) / 32768 * 2.10 \text{ mV/V}$ ;

### Measuring range 10.0 mV/V

**Measuring range ±10 mV/V (set\_gain 0xB2 <p1> <p2>) with p1=ch, p2=0x02**

<i>Input signal in mV/V</i>	<i>Measuring range in %</i>	<i>16 Bit output value (hexadecimal)</i>
10.5	105.00%	FFFFh
10.0	100.00%	F9E7h
0.0	0.00%	8000h
-10.0	-100.00%	0618h
-10.5	-105.00%	0000h

Conversion of digital output value to analogue input signal:

Output value = Highbyte \* 256 + Lowbyte;

Input signal  $U_d = (\text{output value} - 32768) / 32768 * 10.5 \text{ mV/V}$ ;

### Measuring range 0.0 to 5 V

**Measuring range 0-5 V (set\_gain 0xB2 <p1> <p2>) with p1=ch, p2=0x03**

Input signal in V	Measuring range in %	16 Bit output value (hexadecimal)
5.25	105.00%	FFFFh
5.0	100.00%	F9E7h
0.0	0.00%	8000h

Conversion of digital output value to analogue input signal:

Output value = Highbyte \* 256 + Lowbyte;

Input signal  $U_d = (\text{output value} - 32768) / 32768 * 5.25 \text{ V}$ ;

### Measuring range 0.0 to 10 V

**Measuring range 0-10 V (set\_gain 0xB2 <p1> <p2>) with p1=ch, p2=0x07**

Input signal in V	Measuring range in %	16 Bit output value (hexadecimal)
10.5	105.00%	FFFFh
10	100.00%	F9E7h
0.0	0.00%	8000h

Conversion of digital output value to analogue input signal:

Output value = Highbyte \* 256 + Lowbyte;

Input signal  $U_e = (\text{output value} - 32768) / 32768 * 10.5 \text{ V}$ ;

### Measuring range PT1000

**Measuring range PT1000 (set\_gain 0xB2 <p1> <p2>) with p1=ch, p2=0x04**

Input signal in °C	Measuring range in %	16 Bit output value (hexadecimal)
1050	105%	FFFFh
1000	100%	F9E7h
0.0	0.0%	8000h
-40	-4%	6DB0h

Conversion of digital output value to analogue input signal:

Output value = Highbyte \* 256 + Lowbyte;

Input signal  $U_e = (\text{output value} - 32768) / 32768 * 1050 \text{ °C}$ ;

### Measuring range K thermocouple cable

**Measuring range K-thermocouple cable (set\_gain 0xB2 <p1> <p2>) with p1=ch, p2=0x06**

Input signal in °C	Measuring range in %	16 Bit output value (hexadecimal)
--------------------	----------------------	-----------------------------------

**Measuring range K-thermocouple cable (set\_gain 0xB2 <p1> <p2>) with p1=ch, p2=0x06**

1050	105%	FFFFh
1000	100%	F9E7h
0.0	0.0%	8000h
-40	-4%	6DB0h

Conversion of digital output value to analogue input signal:

Output value = Highbyte \* 256 + Lowbyte;

Input signal Ud = (output value - 32768) / 32768 \* 1050 °C;

### Commands for configuration

The code of the command concerned is sent to the measuring amplifier for configuration. Some commands expect parameters, e.g. the channel number “ch” and potentially other bytes.

Note: To set the configuration, the data transfer should be interrupted by sending the command “stop\_transmission”.

After completing the configuration, the data transfer can be restarted again by executing the command “start\_transmission”.

Notes: After each switch-on, the “normal mode” must be set in order to send commands (0x26 01 62 65 72 6C 69 6E).

### List of commands

The table lists the available commands (rev0x0B) and their hexadecimal codes.

Commands	Code	p1	p2	p3	p4	p5	p6	p7	p8	p9
set_zero	0C	ch								
save_configuration	09	B								
restore_configuration	0A	B								
set_offset	0B	ch	B	HB	B	LB				
get_offset	0D	ch	B							
set_frequency	12	B								
get_frequency	16									
get_serial_number	1F									
set_serial_number	1E	B	B	B	B	B	B	B	B	
set_threshold	20	B	HB	LB						
set_threshold	21	B								
stop_transmission	23									
start_transmission	24									

Commands	Code	p1	p2	p3	p4	p5	p6	p7	p8	p9
set_mode	26	B	B	B	B	B	B	B		
get_mode	27									
set_tx_status	28	B								
get_tx_status	29									
get_firmware_version	2B									
get_value	3B									
set_cal_factor	88	ch	HB	B	B	LB				
get_cal_factor	89	ch	B							
set_rs232	B0	ch								
get_rs232	B1									
set_gain	B2	ch	B							
get_gain	B3									
set_unit	B4	ch	B							
get_unit	B5	ch								
set_digital	B6	B								
get_digital	B7									
set_digital_on_off	B8	B	B							
get_digital_port	B9									
set_user_sring	BC	HB	B	B	B	LB				
get_user_sring	BD									
get_bat	BE									
set_user_scale	BA	ch	HB	B	B	LB				
get_user_scale	BB	ch	HB	B	B	LB				
set_can_bitrate	C0	B								
get_can_bitrate	C1									
reserved	C2									
reserved	C3									
set_can_id	C5	B	B	B	B	B				
get_can_id	C6	B								
reserved	C7									
reserved	C8									

Commands	Code	p1	p2	p3	p4	p5	p6	p7	p8	p9
reserved	D0	B	B	B	B	B	B	B		
reserved	D1									
reserved	D2	B	B							
reserved	D3									
reserved	D4									
reserved	D5	B	B							
reserved	D6									

Table 8: Command list for BSC4D (ch = channel number), B = byte, HB = high byte, LB = low byte) Commands in grey are reserved for the initial setup or calibration. The commands shaded grey are only available after restarting.

## Description of commands

### set\_gain (B2)

With the command set\_gain, the 4 inputs on the measuring amplifier can be configured individually for various sensor types.

Parameters in HEX	Description
01	DMS input $\pm 2$ mV/V
02	DMS input $\pm 10$ mV/V
03	Analogue input 0-5 V
04	Input for PT1000 -40°C ... 1000 °C
06	Input for K-thermocouple cable -40°C ... 1000 °C
07	Analogue input 0 – 10 V

### set\_frequency (12)

The data frequency is set with the command set\_frequency. The measurement data is acquired with the data frequency and are ready to be transmitted via the interface. By setting the data frequency, the digital filter is set automatically, see data frequencies and filter properties.

After executing the command “start\_transmission”, the measurement data is transmitted steadily at the set data frequency. After executing the command “stop\_transmission”, the measuring data is only sent when required. It can be requested with the command “get\_value” or for devices with CAN bus via CAN-Sync\_ID (page **Error! Bookmark not defined.**).

Note: Care should be taken to ensure that the request for measured values does not occur more frequently than the set data frequency. Otherwise, a current measured value will not be available every time there is a request. The same measured values are requested repeatedly.

Parameters in HEX	Data frequency in Hz( nominal)	Data frequency in Hz( effective)
A0	0.63	0.625
A1	1.25	1.250
A2	2.5	2.500
A3	3.75	3.750
A4	6.25	6.250
A5	7.5	7.500
A6	12.5	12.400
A7	15	14.700
A8	25	24.400
A9	125	114.000
AA	250	208.000
AB	500	
AC	937.5	
AD	1875	
AE	3750	
AF	7500	

**set\_can\_bitrate (C0) / get\_can\_bitrate (C1)**

Parameters in HEX	Bitrate in kbit/s
10	20
20	50
30	80
40	100
50	125
60	250
70	500 (standard)
80	1000



### save\_configuration (0A) / restore\_configuration (09)

The entire configuration (data frequency, configuration of inputs, etc.) can be saved and restored as a parameter set. Two memories are available for the configuration.

Parameters in HEX	Description
01	Manufacturer setting
02	User setting 1
03	User setting 2

### set\_user\_scale (BA) / get\_user\_scale (BB)

A scaling factor in 32 Bit format can be stored for each channel. This scaling factor is stored in the EEPROM of the measuring amplifier and can be read with get\_user\_scale.

Parameters in HEX	Memory No.	Label
01	1	Channel 1
02	2	Channel 2
03	3	Channel 3
04	4	Channel 4

Number format:

Sign	Index	Significand
Bit 0	Bit 1 ... Bit 8	Bit 9 ... Bit 31

### Protocol for measured values

Measured values are framed by a prefix 0xA5 and a postfix from the sign 0x0D 0x0A (carriage return linefeed).

The entire frame is 11 bytes long.

Prefix	Channel 1		Channel 2		Channel 3		Channel 4		Postfix	
A5	HB	LB	HB	LB	HB	LB	HB	LB	0D	0A

Table 9: Protocol for transmitting the measured values via RS232 interface

### Protocol for commands

After switching on, only the commands:

get\_value (0x3B)

set\_mode (0x26 01 62 65 72 6C 69 6E)

get\_mode (0x27)  
 get\_tx\_status (0x29)  
 get\_firmware\_version (0x2B)

can be used! To be able to use all of the commands, "set\_mode" has to be sent.

Commands begin with the code followed by parameters.

Code		Parameter			
xx	p1	p2	...	pn	

Examples:

Requesting serial number 1F  
 Setting channel 1 to zero: 0C 01

### Protocol for responding to commands

Responses are framed by a prefix 0x3B and a postfix from the sign 0x0D 0x0A (carriage return linefeed).

The entire frame has a variable length. The number of frames still to follow is given with "n". The number of variable bytes is defined in the fourth and fifth Byte with the data word "len". The entire length of the response is (10 + len) bytes.

The command "get\_value" is an exception. The response to this command takes place with a protocol for measured values.

Prefix	Code	n	len		No.			len bytes				Postfix	
3B	xx	B	HB	LB	aa	bb	cc	p1	p2	...	pn	0D	0A

Table 10: Protocol for responding to commands

#### Example: Releasing commands

Send: 0x26 01 62 65 72 6C 69 6E

#### Example: Locking commands

Send: 0x26 00 62 65 72 6C 69 6E

#### Example: Request serial number

Send: 0x23

Send: 0x1F

Receive 0x 3B 1F 01 00 08 30 35 30 30 38 34 34 39 30 35 30 0D 0A

Send 0x24

Result: The serial number is "08449050".

#### Example: Change status(Send measured value OFF/ON)

To permanently save the value send stop or start measured value, the command

set\_tx\_status (0x28<p1>) can be used.

Parameters in HEX	Parameters in Bit	Current	After switching on
00	0 0 0 0 0 0 0 0	Send measured value OFF	Send measured value OFF
01	0 0 0 0 0 0 0 1	Send measured value OFF	Send measured value ON
02	0 0 0 0 0 0 1 0	Send measured value ON	Send measured value OFF
03	0 0 0 0 0 0 1 1	Send measured value ON	Send measured value ON

Send: 0x23  
 Send: 0x29  
 Receive : 0x 3B 29 01 00 01 30 33 33 01 0D 0A

Result: Current-OFF , After switching on-ON

Send: 0x28 02  
 Send: 0x29  
 Receive : 0x 3B 29 01 00 01 30 33 33 02 0D 0A

Result: Current-ON , After switching on-OFF

## Digital IOs

The entire port is always read (IO8 to IO1).

-4Example: Read port

Send: 0x23  
 Send: 0xB9  
 Receive : 0x 3B B9 01 00 01 30 33 33 00 0D 0A

Result: all inputs and outputs are "low"

Parameters in HEX	Parameters in Bit	Port
00	0 0 0 0 0 0 0 0	IO8 IO7 IO6 IO5 IO4 IO3 IO2 IO1

The digital port can be configured with set\_digital (0xB6 <p1><p2>) and set\_digital\_on\_off(0xB8 <p1> <p2>). The port is set with <p1>/

## set\_digital (0xB6 <p1> <p2>)

Parameters in HEX <p2>	Description
------------------------	-------------

Parameters in HEX <p2>	Description
00	Input
01	Output
02	get_Value
0A	Tara all
0B	Tara channel1
0C	Tara channel2
0D	Tara channel3
0E	Tara channel4
11	SW1
12	SW2
13	SW3
14	SW4
15	SW5
16	SW6
17	SW7
18	SW8

### set\_digital\_on\_off(0xB8 <p1> <p2>)

Parameters in HEX <p2>	Parameters in Bit	Port	Description
00	0 0 0 0 0 0 0 0	For IO1 to IO8	OFF
01	0 0 0 0 0 0 0 1	For IO1 to IO8	ON

### Example: Change IO1

Send: 0x23

Send: 0xB6 01 0B

Send: 0xB7

Receive : 0x 3B B7 01 00 02 30 33 33 01 0B 0D 0A

Result: IO1 is configured as Tara for channel1

Send: 0xB6 01 00  
 Send: 0xB7  
 Receive : 0x 3B B7 01 00 02 30 33 33 01 00 0D 0A  
 Send: 0x24

Result: IO1 is configured as an input and can be read with 0xB9

**set\_threshold (0x20 <p1> <p2>)**

Parameters in HEX <p1>	Description	Channel assignment	Switching threshold
01	SW1	1	ON
02	SW1	1	OFF
03	SW2	1	ON
04	SW2	1	OFF
05	SW3	2	ON
06	SW3	2	OFF
07	SW4	2	ON
08	SW4	2	OFF
09	SW5	3	ON
0A	SW5	3	OFF
0B	SW6	3	ON
0C	SW6	3	OFF
0D	SW7	4	ON
0E	SW7	4	OFF
0F	SW8	4	ON
10	SW8	4	OFF

By setting the on and off switching thresholds differently, a hysteresis can be programmed. The second parameter (<p2>) is the switching threshold in HEX e.g.: 0x89 FF.

**Caution:** in order to compare the threshold value with the measured value directly, it has to be added with 0x80 00.

**Example: Configuration of SW1 IO8 ( or digital 5)**

Send: 0x 23  
 Send: 0x B6 08 11

Configure IO8 for SW1

Send: 0x 20 01 01 00

The turn-on threshold of SW1 is set to 0x81 00.

Send: 0x 20 02 FE 00

The turn-off threshold of SW1 is set to 0x7E 00.

If the measured value increases above 0x81 00, IO8 is switched on. If the measured value falls below 0x7E 00, IO8 is switched off.

## Analog input

### Example: Requesting the configuration of analog inputs

Send: 0x23

Send: 0xB3

Receive : 0x 3B B3 01 00 04 30 35 30 01 01 02 03 0D 0A

Send 0x24

Result: Channel 1 = 2 mV/V, channel 2 = 2 mV/V, channel 3 = 10 mV/V, channel 4 = 0-5 V;

### Example: Setting the configuration of analog inputs

Specification: configuring channel 1 to channel 4 for PT1000

Send: 0x23

Send: 0xB2 01 04

Send: 0xB2 02 04

Send: 0xB2 03 04

Send: 0xB2 04 04

Send 0x24

### Example: Setting the data frequency to 12.5 Hz

Specification: The measured value should be sent steadily with a frequency of approx. 12.5/s.

Send: 0x23

Send: 0xA6

Send 0x24

## Data frequency and filter

### Analog filter

The integrated analog filter is a first-order low-pass filter with a cut-off frequency of 1 kHz. It is set as an *antialiasing* filter for the A-D converter. This filter is permanently installed and cannot be changed.

### Digital filter

The digital filter is indirectly set with the data frequency. The effective data frequency may differ slightly from the set (nominal) data frequency. The grey shaded settings are recommended as with these settings faults with a mains frequency of 50 Hz are best suppressed by the integrated “notch filter”.

Data frequency in Hz (nominal)	Data frequency in Hz (effective)	Notch frequency in Hz	-3db cut-off frequency in Hz (digital filter)	Parameters for “set frequency”
250	208	1000	441	0xAA
125	114	500	221	0xA9
25	24.4	100	44.2	0xA8
15	14.7	60	26.5	0xA7
12.5	12.4	50	22.1	0xA6
7.5	7.5	30	13.3	0xA5
6.25	6.25	25	11.1	0xA4
3.75	3.75	15	6.63	0xA3
2.5	2.5	10	4.42	0xA2
1.25	1.25	5	2.21	0xA1
0.625	0.625	2.5	1.1	0xA0

Table 14: data frequencies and filter properties

## BSC4 Mounting Kit

The BSC4 comes with a bracket kit suitable for mounting the unit to a wall or plate.


Contents:

4X Wall Brackets

4X Screws for attaching the brackets to the housing

4X Bracket seals

Required tools: T10X80 Torx driver.



Carefully remove the black plugs shown in the picture above and remove the Torx screws underneath. Press the black rubber seals into the holes and use the black Torx screws provided with the mounting kit to attach the brackets.

The mounting feet can be oriented either inboard or outboard as needed.